

Total Rebuild Cost Value (Incl. VAT):	£13,364,586
Total Rebuild Cost Value (Excl. VAT):	£11,137,155

Report Prepared For:	Sample Report - Enhanced Commercial Desktop
Rebuild Cost Assessment Ref:	54763132
Policy Reference:	Not Advised
Property Address:	Mey House Bridport Road Poundbury
Postcode:	DT1 3QY
Date of Assessment:	21/06/2024
Assessed By:	Elliot Robson
Completed By:	Richard Hindley AssocRICS
For and on behalf of Rebuild Cost Assessment Regulated by RICS	
For Queries Please Contact:	<a href="mailto:info@rebuildcostassessment.com">info@rebuildcostassessment.com</a> 01305 215535



To help you understand this report, its contents and some of the technical aspects, we have produced a simple overview video which you can find by clicking on the button below

WATCH REPORT OVERVIEW VIDEO

You will also find buttons which link to further explainer videos throughout our report. You may also find the [FAQ section](#) of our website helpful. We hope our report meets your needs and expectations and thank you for using our service. We're glad to have been given the opportunity to assist you in ensuring your property is adequately protected.

The Rebuild Cost Assessment must be read in conjunction with the Instructions and Basis of Assessment detailed later in this report.



Copyright in this report belongs to or is licensed to Rebuild Cost Assessment Ltd and no permissions or licences in relation to this report are granted save as expressly set out in writing by Rebuild Cost Assessment Ltd. No part of this report may be reproduced in any form or for any purpose without the prior permission of Rebuild Cost Assessment Ltd.

## SUMS INSURED & DURATION

### Rebuild Cost Assessment

	Current Sums Insured	RCA Ex VAT	RCA Inc VAT
Main Buildings:	Not Advised	£11,023,155	£13,227,786
Other Permanent Structures:	Not Advised	£114,000	£136,800

[SUMS INSURED VIDEO](#)

### How long will the rebuild take?

Using BCIS and other industry standard quantity surveying data, we suggest that you allow for a sufficient total rebuild period as stated below should a complete rebuild be required. Please see notes within the INSTRUCTIONS AND BASIS OF ASSESSMENT section for more detail.

TOTAL REBUILD PERIOD	33 months
Pre-Construction Period: design, planning, demolition etc	12 months
Construction Period (BCIS supplied)	21 months
Additional Comments	N/A

[REBUILD PERIOD VIDEO](#)

### How often should there be a reassessment?

We would recommend this property is reassessed as stated below. Please discuss with your broker or insurance agent with regards to indexing these rates for the next period prior to a reassessment. Costs of materials and labour in the construction industry have risen faster than general inflation in the last few years. Any structural changes, extensions, or changes of use to the property will require a new Rebuild Cost Assessment.

Recommended Reassessment Date	21/06/2027
Additional Comments	N/A

[REASSESSMENT VIDEO](#)

## THE CALCULATION

<b>Main Property</b>			<b>Exc. VAT</b>	<b>Inc. VAT</b>
Lower Ground Floor parking	1779 m <sup>2</sup> ×	£1,100 per m <sup>2</sup>	£1,956,900	£2,348,280
Lower Ground Floor Offices	327 m <sup>2</sup> ×	£2,100 per m <sup>2</sup>	£686,700	£824,040
Ground floor - Offices total	1934 m <sup>2</sup> ×	£2,100 per m <sup>2</sup>	£4,061,400	£4,873,680
Ground floor - Canopy	150 m <sup>2</sup> ×	£400 per m <sup>2</sup>	£60,000	£72,000
First floor - Offices	698 m <sup>2</sup> ×	£2,100 per m <sup>2</sup>	£1,465,800	£1,758,960
Second floor - Offices	567 m <sup>2</sup> ×	£2,100 per m <sup>2</sup>	£1,190,700	£1,428,840
<b>Main Property Sub Total</b>			<b>£9,421,500</b>	<b>£11,305,800</b>

<b>Other Cost Factors</b>				
Professional Fees at	10 %		£942,150	£1,130,580
Demolition at	7 %		£659,505	£791,406
<b>Sub Total</b>			<b>£1,601,655</b>	<b>£1,921,986</b>

<b>Other Permanent Structures (OPS)</b>			<b>Exc. VAT</b>	<b>Inc. VAT</b>
Car Parks, Walls, Gates, etc.			£100,000	£120,000
<b>OPS Sub Total</b>			<b>£100,000</b>	<b>£120,000</b>

<b>Other Cost Factors</b>				
Professional Fees at	7 %		£7,000	£8,400
Demolition at	7 %		£7,000	£8,400
<b>Sub Total</b>			<b>£14,000</b>	<b>£16,800</b>

	<b>Exc. VAT</b>	<b>Inc. VAT</b>
<b>Total Estimated Main Property Rebuild</b>	<b>£11,023,155</b>	<b>£13,227,786</b>
<b>Total Estimated OPS Rebuild</b>	<b>£114,000</b>	<b>£136,800</b>
<b>Total Rebuild Cost Assessment</b>	<b>£11,137,155</b>	<b>£13,364,586</b>

## JUSTIFICATION OF RATES & VAT

### Heritage Information

Listed:	Not Listed
Conservation Area:	No
Conservation Area Name (If Applicable):	

### How was the rate calculated?

BCIS (Building Cost Information Service) is an independent cost data provider that we use where applicable to inform our assessments. However, it may not always be suitable for all property types, and in such cases, other industry-standard quantity surveying data may be utilised. As a RICS-regulated firm, our valuations adhere to professional standards, ensuring accuracy and reliability. Professional fees and demolition costs have been included to account for anticipated expenses such as re-design, structural engineering, project management, site clearance, and debris removal. Our measurements are based off Gross External floor areas.

BCIS Category	320/125.4
BCIS Description	Offices/Car parks (Underground)
Other Quantity Surveying Data Sources	Industry Data
Total Floor Area	5,455 m <sup>2</sup>
Main Rebuild Rate	£2,100 per m <sup>2</sup>
Range	Lower Quartile to Median
BCIS Location Index	105 West Dorset
Additional Comments	N/A

### Should I include VAT?

We would always recommend that you obtain professional advice from an accountant or local VAT office before making a decision to include or not include VAT within the sums insured. The Assessment includes a VAT breakdown and you can include or remove any element of VAT from the VAT breakdown as appropriate depending on the advice you receive.

[VAT VIDEO](#)

## DESCRIPTION

### Property Details

Main Building Material	Steel and concrete frame, brick and stucco with reconstituted stone accents
Roof Type and Material	Hipped, slate
Window Type and Material	Aluminium, picture and casement windows
Number of Floors (excluding basement)	3
Basement (Yes / No / Finished / Unfinished)	Yes - Lower ground floor
Year of Build (if listed)	N/A
Usage	Commercial, offices
Attached Structures / Extensions	Covered area
Outbuildings Structure / Usage	N/A
Other Permanent Structures (OPS)	Car park, paving, walling, and external steps

### Information Sources Include

Google Earth	Yes	
Find Maps	Yes	
Zoopla	N/A	
Rightmove	N/A	
Historic England	Yes	
Local Planning Authority	N/A	
Valuation Office	Yes	<a href="#">View</a>
Street View	Yes	<a href="#">View</a>
Bing Maps	Yes	<a href="#">View</a>
Any Other Information	N/A	

### Additional Comments

1. From speaking with the client on 20/06/2024, they confirmed the extent of the lower ground parking area.

PHOTOGRAPHS



Google  
Street View




Google  
Street View





Google  
Aerial View



Map View

## 1. INSTRUCTIONS AND BASIS OF ASSESSMENT

- 1.1 Our rebuild cost assessment (the **Assessment**) is an estimate of the rebuilding costs in the event of a total loss of the property. This is based on the gross external area and typical rebuild rates per square metre for the building use, type/quality of construction, and excludes the contents of the property.
- 1.2 The external square meterage of the property is obtained from the site survey and available data. For desktop assessments, the external square meterage of the property is obtained from Ordnance Survey and other available data with an appropriate rebuild rate applied to each floor. We may use IPMS subject to individual property type and the information we have available.
- 1.3 The Assessment is not derived from a detailed measured estimate, measured cost plan or bill of quantities.
- 1.4 Desktop assessments are limited to rebuild values of £5,000,000 for residential properties and £12,000,000 for commercial properties. Should the desktop assessment exceed these values, the report will become indicative and another product will be required.
- 1.5 Once the assessment process has commenced, the research may highlight that the property is unsuitable for a desktop assessment. The assessment process will cease and another product or refund will be offered.
- 1.6 Each desktop assessment will allow for a singular postcode. Requests for properties at multiple locations will need to be processed on individual reports.
- 1.7 With the exception of properties located within Scotland, all buildings must be assessed in their entirety, partial/individual floors or selected sections cannot be completed separately.
- 1.8 Each desktop assessment contains a mixture of actual building and additional items such as tennis courts/swimming pools etc. Each desktop assessment will allow for a maximum of 7 such items. Requests for locations within the same postcode but for more than 7 items will need to be split across multiple reports.

Where multiple properties are requested on a singular report, the professional fees and demolition fees will not be individually identified.
- 1.9 The Assessment is valid for 12 months from the date of survey. Reasonable amendments can be made to the report:
  - 1.9.1 within the first 6 months where requested by the client; and
  - 1.9.2 within the 12 month period if a substantial error has been found on the part of Rebuild Cost Assessment.
- 1.10 If the Assessment was completed using the information provided to Rebuild Cost Assessment by the instructing party and subsequent changes are required with information which is different from that which was originally provided, this will attract an additional charge. By way of example, if a requested address was Unit 1 and the required amendment is for Unit 1-3, the additional units were not originally requested and would be chargeable.



- 1.11 It is essential that the recipient of the assessment thoroughly examines all the information provided within the assessment to ensure its accuracy and completeness. Should they identify any discrepancies, errors, or inconsistencies in the report, it is their responsibility to promptly notify us. Immediate contact is crucial so we can address any anomalies. This proactive approach helps ensure that the assessment is both accurate and fully reflects the intended analysis, preventing any potential issues or misunderstandings down the line.

## 2 THE ASSESSMENT

### ***Costs included in the Assessment***

- 2.1 In calculating the Assessment figure we have:
- 2.1.1 included an appropriate sum to cover the cost of debris removal, architects, consulting engineers, and surveyors fees. Please note a higher level of fees could apply if the property was partially damaged. The sum we have included has been calculated on the basis of a total loss and assumes that no original architectural, engineering or surveying documentation is available to be re-used;
  - 2.1.2 included an appropriate sum to cover the cost of complying with the current Building Regulations;
  - 2.1.3 made an allowance to take into consideration the listing of the property and its location in any conservation area and/or world heritage site;
  - 2.1.4 made an allowance for foundations appropriate to the existing building, except those specified in paragraph 2.2.1 below;
  - 2.1.5 made an allowance for other permanent structures adjacent to the property reasonably assumed part of the property.

### ***Costs excluded from the Assessment***

- 2.2 In calculating the Assessment figure we have:
- 2.2.1 excluded piled foundations and ground improvement costs from the Assessment, unless noted in the comments section of the report;
  - 2.2.2 made no allowance for road closures or diversion of major services;
  - 2.2.3 made no allowance for any amount required for excavation, replacement, or stabilisation of land under or around the property including shoring up and support during the demolition phase.
  - 2.2.4 made no allowance for any costs of demolition of pre-stressed or post tensioned concrete structures appropriate to the building
  - 2.2.5 made no allowance for any value in salvaged materials;

- 2.2.6 made no allowance for any cost of the removal of any deleterious materials (including asbestos) or any improvements needed to contaminated land found post demolition of the property or other permanent structures;
- 2.2.7 made no allowance for any fees arising from any issues referred to in clause 2.2.6 above. The necessity, extent and cost of such work cannot be reasonably determined without a detailed investigation beyond the scope of the rebuild cost assessment;
- 2.2.8 made no allowance for the inflation, the assessment day one assessment at the date of the report.
- 2.2.9 Considerations of the terms and conditions of lease provisions for the residential and commercial leasehold building are outside the remit of the report however in general terms for tenanted buildings we have made no allowance for occupiers fitting out works, fixtures fittings or furnishings. However, in assessing the extent of the building structure, services, and fittings, we have made reasonable assumptions in respect of the inclusion of items which may have been installed by tenants but which, by nature of their degree of permanence or annexation to the structure have insured to the benefit of the owner, i.e. Kitchens and bathrooms,
- 2.2.10 made no provision in respect of process, plant and machinery, fitting out works and the like, in respect of which, further advice should be taken;
- 2.2.11 made no allowance for upgrading or improvements that may be incorporated in the redesign of the property.
- 2.3 We have also excluded:
  - 2.3.1 from the external works in the Assessment:
    - (a) allowances for all trees, shrubs and soft landscaping and grassed areas; and
    - (b) allowance for all pumps, tanks, fuel lines; and
    - (c) allowances for all pontoons, jetties, and sea defences.
    - (d) allowances for all bridges and retaining walls to highways unless deemed appropriate
    - (e) allowances for the pavement or road construction above vaults which would be subject to local authority involvement.
    - (f) allowances for all recreational turf grounds, for example bowling greens, sports pitches, etc.
  - 2.3.2 from the Assessment claim negotiations fees for loss assessors.

## ***Rebuild Period***

- 2.4 The time it takes to rebuild the property will be influenced by many factors including, but not limited to, the nature of the event that caused the destruction, the extent of damage, the drafting of plans and securing of permissions, the availability of labour. For example, any reconstruction work may be delayed due to the need to consult interested parties e.g. a mortgage company. It can also take time to source suitable building materials and draw up revised plans which will meet current Building Regulations. These will extend the period of reconstruction. Therefore, depending on the property, greater inflationary factors may need to be taken into account than stated industry standards. This is outside the remit of our services.
- 2.5 Site survey rebuild periods have been calculated using the information obtained from a site survey and comparable construction data.
- 2.6 Desktop rebuild periods have been calculated using the available remote information and comparable construction data for a desktop assessment.
- 2.7 For all construction periods, a longer duration may be required based on specific, individual circumstances.
- 2.8 The period given assumes that planning and rebuilding proceeds expeditiously to completion following the event.

## **3 VAT**

- 3.1 The Assessment does not extend to advising you on whether all or any elements of your rebuild cost will incur VAT and thus need to be included when determining the building sum insured for insurance purposes.
- 3.2 Consequently, the Assessment will always include a VAT breakdown at UK standard rates for all elements of the rebuild cost and it is entirely at your discretion and risk as to whether you choose to include VAT on all or any element when arranging your insurance policy. We recommend you seek independent advice on the application of VAT.

## **4 ASSUMPTIONS AND PRINCIPLES ADOPTED FOR THE ASSESSMENT**

- 4.1 The Assessment is our opinion of the rebuild cost estimate of the property for insurance purposes using current rebuilding costs and assumes tenders are sought in competition or realistically negotiated and is not related to the open market value of the site or the building.
- 4.2 Our Assessment is based on the assumption that the property is totally destroyed or damaged to such an extent that total reconstruction is required.
- 4.3 Our Assessment does not make any comments, recommendations, or assumptions regarding the materials, installation, or compliance of external wall systems used in any project. We are not responsible for assessing or verifying the suitability or safety of external walls, nor do we offer any expertise on external wall-related matters. Any external wall systems installed must comply with all applicable building regulations and standards. It is the responsibility of the building owner, developer, contractor, or other relevant parties to ensure that external wall materials and installation processes adhere to the required codes and standards.

For specific advice regarding external wall compliance, we recommend you consult a qualified building surveyor, fire safety consultant, or other relevant professionals who can provide tailored guidance based on the individual project.

- 4.4 The Assessment assumes that rebuilding of the property in its present size, form, specification, and position will be permitted by the Local Authority in relation to:
  - 4.4.1 Current Building Regulations. Please seek advice from your Local Authority regarding current required regulations at the time of rebuild;
  - 4.4.2 Local Authority Planning Policy. Such policy, which determines the extent to which sites may be developed, varies from time to time and we recommend you clarify the position with the Local Authority.
  - 4.4.3 Unless advised otherwise, a desktop assessment will assume the internal specification is to be of a standard nature typical for the size and type of property.
  - 4.4.4 Where external imagery is not available, a desktop assessment will assume all construction methods are of a similar design, style, and specification to those visible in available imagery at the time of assessment
  - 4.4.5 Unless advised otherwise, a desktop assessment will assume the property usage as the last recorded usage.
  - 4.4.6 Unless advised otherwise, a desktop assessment will take measurements using the most recently available ordinance survey and aerial information and other online sources.

## 5 LISTED BUILDINGS – SPECIAL NOTES

- 5.1 Depending upon the category of listing and the viewpoint of the relevant Local Authority conservation officer, the ability to use modern construction methods and/or materials will vary considerably.
- 5.2 Where the property, or part thereof, is listed, the Assessment assumes the use of modern construction techniques and modern materials where appropriate. The exception to this is where the use of historic methods of construction and materials, along with the salvaging and reuse of existing materials, is essential to the preservation of the historic character of the property and/or where there is a specific condition within the property listing.

(BOA092025)

## DISCLAIMER

### IMPORTANT NOTICE

This report (**Report**) is confidential and has been prepared by Rebuild Cost Assessment Limited (company number 09746801) for the provision of a rebuild cost assessment of the building the subject matter of the Report (**Purpose**). The Report has been prepared for the benefit of:

- (a) The Intermediary (being the entity that has commissioned this Report);
- (b) The Client (being the owner or occupier or proposed purchaser of the building to which this Report relates); and
- (c) The Insurance Company (being an insurance company with whom the Intermediary acts as an intermediary between that insurance company and the Client); together (the **Recipients**).

The Recipients and anyone else receiving this Report must treat it as confidential.

This Report may not be copied or disclosed to any person in whole or in part or used for any purpose other than the Purpose. No one other than the Recipients may rely on this Report.

Save for the warranty that the Report has been prepared using reasonable skill and care, all warranties, conditions and other terms implied by statute or common law are excluded to the fullest extent permitted by law. Without prejudice to the foregoing, the maximum aggregate liability of Rebuild Cost Assessment Limited and its employees, officers, agents and sub-contractors for any liability and losses of whatever kind and howsoever arising (including negligence), as a result of access to, use of, or reliance upon, any information contained in this Report is limited to £1,000,000 (one million pounds), unless otherwise stated in a contract. Neither Rebuild Cost Assessment Limited nor its employees, officers, agents or sub-contractors shall be liable to any person for indirect, consequential or special losses. In no circumstances shall Rebuild Cost Assessment Limited or its employees, officers, agents or sub-contractors be liable to any person other than the Recipients or where the Report has not been used for the Purpose.

Nothing in this disclaimer shall limit or exclude the liability of Rebuild Cost Assessment Limited to the extent that such liability cannot be lawfully limited or excluded.

To view our terms and conditions, please [click here](#)

(Ref. BR 202405)